## RCRA Groundwater Monitoring Program 2440 Stevens Center, Room 1560 Richland, Washington February 4, 1994

Approval:

Date: 2/8/52

B. A. Williams, Geohydologic Engineering Westinghouse Hanford Company, Richland, Washington

8. A. Williams

Date: 2/16/94

K. Kowalik, State of Washington

Department of Ecology

H6-06

<u>Attendees</u>	<u>Distribution</u>
State of Washington Department of Ecology	Attendees G. C. Evans H6-23 K. R. Fecht H6-06 R. L. Jackson H6-05
K. Kowalik	J. F. Keller L4-93 K. D. Reynolds H6-06
Yestinghouse Hanford Company	- W. R. Thackaberry H4-16 -RR. Thompson -H6-32 

## Summary of Meeting Minutes

In a brief meeting with the State of Washington Department of Ecology, it was decided that a variance was not required for the missing seal interval in Resource Conversation and Recovery Act (RCRA) well 299-E25-1000 which was installed to monitor the Grout Treatment Facility (GTF) in CY 1993. An internal Westinghouse Hanford Nonconformance Report (NCR #050961) will be sufficient documentation and disposition of this incident. The GTF is no longer monitored as a RCRA facility.

